

Project Profile: QPR FC Stadium

Project: QPR Stadium, Lighting Mast Repair

Client: QPR Holdings Limited



The project: Queens Park Rangers Football Club Stadium, located in Shepherds Bush, London, identified an issue with one of their lighting masts in the summer of 2015, where urgent repairs were necessary, with the bases of this mast beginning to corrode and crack.

APA Concrete Repairs Ltd were therefore appointed to undertake the repair and reinstatement of this lighting mast within the stadium.



The solution: The concrete surrounding the defective fixing of the mast was first broken out, in order to facilitate the Ancon coupler and new bolt, which were installed and tightened to the required tension. Existing concrete surfaces were primed, and new concrete was instated to form the original concrete profile, before a new stiffener plate was welded to the existing corroded stiffener. Upon completion, the exposed steel was coated to provide additional weather protection.



The outcome: The repairs were completed in July 2015, with the outcome resulting in the mast being promptly put back into service, just in time for the commencement of the new football season in August.



Materials Utilised:

- Hanson C40 Concrete
- Parex Acrylic Latex Bonder
- Zinc Rich Epoxy Paint
- Parex CS Grout

For further enquires please contact:

E-mail: sales@apaconcretereairs.co.uk

Tel: 01422 379640

Northern Office

Black Brook Way
Greetland
Halifax
West Yorkshire
HX4 8ED
Telephone: 01422 379 640
Fax: 01422 374 938

Southern Office

Abbey House
Wellington Way
Brooklands Business Park
Weybridge
London
KT13 0TT
Telephone: 0208 853 0627

E-mail: info@apaconcretereairs.co.uk

Web: www.apaconcretereairs.co.uk

PROFESSIONAL MEMBERSHIPS & ACCREDITATIONS HELD

